



DONNING Tier 1


Equipment



Impermeable Boot Covers
 Impermeable, Single Use Coverall
 Surgical Hood
 Powered Air Purifying Respirator (PAPR)
 Nitrile Gloves - 2 Pair
 Scrubs
 Alcohol-based Hand Rub (ABHR)
 Waste Receptacle
 Tape

PPE DONNING Tier 1 Personal Protective Equipment

Preparation



1. Inspect equipment for integrity 2. Perform hand hygiene 3. Apply scrubs and plastic, washable footwear 4. Remove jewelry 5. Hydrate 6. Check vital signs

Application







1. Apply surgical hood* 2. Apply gloves

(Cont'd on Page 3)

^{*}All ties should be properly secured with a simple bow.

PPE DONNING Tier 1

Personal Protective Equipment

Application (Cont'd)



3. Apply coverall 4. Apply boot covers 5. a) Check PAPR connection b) Secure to waist c) Apply PAPR hood d) Secure inner hood layer inside coverall 6. Apply outer gloves 7. Apply tape to outer gloves* 8. Complete Tier 1 PPE

^{*} Outer gloves may be taped to coverall if copious amount of bodily fluids are present or if using coveralls without thumb hooks in the sleeves, and use of tape does not hinder the doffing process.